INSPECTION SUMMARY

Mitsubishi ASX 2017

JE4LP21U8HZ704403 | 153083 KM | GCC Specs

VEHICLE SPECIFICATIONS

MAKE **Mitsubishi**	MODEL **ASX**	VARIANT **-**	YEAR **2017**
VIN / CHASSIS **JE4LP21U8HZ704403**	MILEAGE **153083 KM**	VEHICLE COLOR **Blue**	SPECIFICATIONS **GCC**
KEY **1 Key**	NO. OF CYLINDERS **4**	BODY TYPE **Hatchback**	SEATING CAPACITY **5 Seats**
FUEL TYPE **Petrol**	ENGINE CC **2000 CC**	DRIVE TYPE **2 Wheel**	

SECTION SUMMARY SCORES

CHASSIS & ACCIDENT **87.5%** 16/22 rated	ENGINE & GEARBOX **100.0%** 12/12 rated	BODY & PAINT **70.0%** 15/15 rated
COMPUTER SCAN & ELECTRICAL **100.0%** 18/18 rated	SUSPENSION, BRAKES & TYRES **90.9%** 11/11 rated	SHORT ROAD TEST **92.9%** 7/7 rated

Score basis: Pass 100 | Attention 50 | Fail 0 | N/A excluded

CUSTOMER & INSPECTION DETAILS

Customer: Vinoth Kumar K Mobile: Plate: DXB Inspector: Muhammad

VEHICLE PHOTOS



Left Front Photo



Front

SAMPLE



Right Front Photo



Right Rear Photo




Back



Left Rear Photo



Roof



Front Interior




Back Interior



Instrument Cluster

SAMPLE



Key



Engine Bay



VIN Photo

INSPECTOR COMMENTS & RECOMMENDATION

Bonnet, right back door and trunk replaced. Right center pillar repaired. Right quarter panel inside repainted. Trunk floor minor repaired. Right back and center pillar HIT. Multiple dents on body. Passenger airbag replaced.

COMPLETE INSPECTION CHECKLIST

CHASSIS & ACCIDENT	
Left Front Chassis	PASS
Right Front Chassis	PASS
Left Apron	PASS
Right Apron	PASS
Right Rear Chassis	PASS
Left Rear Chassis	PASS
Radiator Support	PASS
Front Cross Member	PASS
Rear Cross Member	PASS
Right A Pillar	Repainted

SAMPLE

Right B Pillar	ORIGINAL
Right C Pillar	Repainted
Right D Pillar	ORIGINAL
Trunk Floor	Repaired
Left D Pillar	ORIGINAL
Left C Pillar	ORIGINAL
Left B Pillar	ORIGINAL
Left A Pillar	ORIGINAL
Visible Welding or Cutting	PASS
Visible Structural Repair	ATTENTION
Flood Sign	PASS
Fire Sign	PASS

ENGINE & GEARBOX

Engine starting condition	PASS
Abnormal engine noise	PASS
Engine vibration	PASS
Engine oil level and condition	PASS
Coolant level and condition	PASS
Visible engine oil leakage	PASS
Visible coolant leakage	PASS
Engine mounts	PASS
Exhaust smoke	PASS
Gear selection delay	PASS
Gear shifting / transmission operation	PASS
Visible gearbox leakage	PASS

BODY & PAINT

Windshield	CLEAN / ORIGINAL
Front Bumper	S
Bonnet / Hood	S,XX
Right Front Fender	S
Right Front Door	S
Right Back Door	S,XX
Right Quarter Panel	S

SAMPLE

Roof	CLEAN / ORIGINAL
Trunk	S,XX
Rear Bumper	S
Rear Windshield	CLEAN / ORIGINAL
Left Quarter Panel	CLEAN / ORIGINAL
Left Back Door	CLEAN / ORIGINAL
Left Front Door	CLEAN / ORIGINAL
Left Front Fender	S

BODY & PAINT CODE MEANINGS

CLEAN — Clean / Original	XX — Replaced	D1 — Minor Dent
D2 — Major Dent	S — Showered	P — Poligated Showered
A1 — Minor Scratch	A2 — Major Scratch	C — Corrosion / Rusted
B — Broken		

COMPUTER SCAN & ELECTRICAL

Engine diagnostic fault codes	PASS
Transmission diagnostic fault codes	PASS
ABS diagnostic fault codes	PASS
Airbag diagnostic fault codes	PASS
Dashboard warning lights	PASS
Airbag Warning Light	PASS
Battery condition	PASS
AC cooling	PASS
Power windows	PASS
Central locking	PASS
Multimedia / display	PASS
Reverse camera	PASS
Left Headlamp	PASS
Left Side Indicators	PASS
Right Headlamp	PASS
Right Side Indicators	PASS
Right Taillamp	PASS
Left Taillamp	PASS

SAMPLE

SUSPENSION, BRAKES & TYRES

Suspension noise	ATTENTION
Steering play or noise	PASS
Shock absorber leakage	ATTENTION
Brake performance	PASS
Brake warning light	PASS
Left Front Tyre	PASS
Tire Manufacturing Year	2022
Right Front Tyre	PASS
Tire Manufacturing Year	2022
Right Rear Tyre	PASS
Tire Manufacturing Year	2022
Left Rear Tyre	PASS
Tire Manufacturing Year	2022
Spare Tyre Condition	PASS
Wheel / Rim Condition	PASS

SHORT ROAD TEST

Engine acceleration	PASS
Gear shifting during drive	PASS
Steering alignment	PASS
Suspension noise during drive	ATTENTION
Brake operation	PASS
Abnormal vibration	PASS
Warning lights during drive	PASS

ISSUES & FINDINGS

ATTENTION **Right A Pillar**

Repainted

ATTENTION **Right C Pillar**

Repainted

SAMPLE

ATTENTION **Trunk Floor**
Repaired



ATTENTION **Visible Structural Repair**
Right quarter panel, center pillar and trunk floor



ATTENTION **Front Bumper**
S

ATTENTION **Bonnet / Hood**
S,XX

ATTENTION **Right Front Fender**
S

ATTENTION **Right Front Door**
S

ATTENTION **Right Back Door**
S,XX

ATTENTION **Right Quarter Panel**
S

ATTENTION **Trunk**
S,XX

ATTENTION **Rear Bumper**
S

ATTENTION **Left Front Fender**
S

ATTENTION **Suspension noise**
Noisy



SAMPLE

ATTENTION **Shock absorber leakage**


Damage



ATTENTION **Suspension noise during drive**

Need maintenance


DAMAGE PHOTOS




Damage photo 1 — Right center pillar repaired



Damage photo 2 — Right back door replaced



Damage photo 3 — Right quarter panel inside repainted



Damage photo 4 — Trunk replaced



Damage photo 5 — Trunk replaced

SAMPLE

SIGNATURES



Inspector signature



Customer signature

SAMPLE REPORT

Customer report access omitted from this sample.

SAMPLE