INSPECTION SUMMARY

Porsche CAYENNE GTS 92A 2016

WP1ZZZ92ZGLA76381 | 125861 KM | GCC Specs

VEHICLE SPECIFICATIONS

MAKE	MODEL	VARIANT	YEAR
Porsche	CAYENNE GTS	92A	2016
VIN / CHASSIS	**MILEAGE**	**VEHICLE COLOR**	**SPECIFICATIONS**
WP1ZZZ92ZGLA76381	125861 KM	White	GCC
KEY	**NO. OF CYLINDERS**	**BODY TYPE**	**SEATING CAPACITY**
1 Key	6	SUV	5 Seats
FUEL TYPE	**ENGINE CC**	**DRIVE TYPE**	
Petrol	3600 CC	4 Wheel	

SECTION SUMMARY SCORES

ENGINE & TRANSMISSION	FRONT	RIGHT
80.6%	85.7%	60.0%
18/23 rated	7/11 rated	10/10 rated
BACK	**LEFT**	**ROOF**
80.0%	60.0%	90.0%
5/8 rated	10/10 rated	5/6 rated
FRONT INTERIOR	**BACK INTERIOR**	**DASHBOARD**
100.0%	100.0%	93.8%
10/10 rated	8/10 rated	16/16 rated
SUSPENSION & STEERING	**BRAKE**	**CHASSIS & ACCIDENT**
81.8%	83.3%	100.0%
11/16 rated	6/9 rated	1/9 rated
EXHAUST & EMISSIONS	**TIRES & WHEELS**	**SAFETY SYSTEM (AIRBAGS)**
100.0%	100.0%	100.0%
5/7 rated	3/7 rated	1/12 rated
FEATURES & OPTIONS	**ROAD TEST**	
100.0%	94.4%	
27/30 rated	9/9 rated	

Score basis: Pass 100 | Attention 50 | Fail 0 | N/A excluded

SAMPLE

OVERALL INSPECTION RECOMMENDATION

PURCHASE GUIDANCE

NOT RECOMMENDED IN CURRENT CONDITION

Significant mechanical, structural, safety or condition risks were identified. Purchase is not recommended in the vehicle's current condition.

CONDITION

FAIL

87.8 / 100

REPAIR PRIORITY **IMMEDIATE**

KEY ITEMS REQUIRING ATTENTION

- Engine block oil leakage: Major Leakage
- Engine head noise: Major Noise
- Transmission oil leakage: Major Leakage
- Engine oil level / condition: Need to change

Advisory assessment only - not a warranty, valuation or guarantee. The final purchase decision remains with the customer.

CUSTOMER & INSPECTION DETAILS

Customer: Harry Mobile: Plate: AJM 77677 Inspector: Muhammad

VEHICLE PHOTOS



FR left side



Front



FR right side



RR right side

SAMPLE



Back



RR left side



Roof




FR interior



RR interior



Dashboard




Multimedia



Instrument cluster

SAMPLE



Key



Trunk




Spare wheel



Rim / Wheel




Engine bay



VIN

VEHICLE BODY CONDITION DIAGRAM

AMPI



USED CODE MEANINGS

S — Paint Shower / Spray Only

SAMPLE

INSPECTOR COMMENTS & RECOMMENDATION

Engine block oil leakage. Gear major oil leakage. Engine Cam noise. Right side Gear Axle Leakage. Air suspension pump need to replace. Overall car outside and inside repainted

COMPLETE INSPECTION CHECKLIST

ENGINE & TRANSMISSION	
Cold start performance	PASS
Engine oil level / condition	ATTENTION
Radiator	PASS
Condenser	PASS
Fan assembly	PASS

AC Compressor	PASS
Battery	PASS
Engine mounts	PASS
Belts and hoses	PASS
Air filter box	PASS
Engine head oil leakage	PASS
Engine block oil leakage	Major Leakage
Engine oil pan leakage	PASS
Alternator	PASS
Engine head noise	Major Noise
Engine crank noise	PASS
Engine vibration	PASS
Engine wiring	PASS
Supercharged	NA
Turbocharged	PASS
Transmission oil leakage	Major Leakage
Transmission mount	PASS
Transmission noise	PASS

FRONT

Bumper	Repainted
Bumper grill	PASS
Bumper Reinforcement	PASS
Bonnet	Repainted
Upper support	ORIGINAL
Lower support	ORIGINAL
Right headlamp	PASS
Left headlamp	PASS
Windshield	PASS
Wiper	PASS
Windshield washer	PASS

RIGHT

Right Fender	Repainted
Right Front Door	Repainted

SAMPLE

Right Rear Door	Repainted
Right Quarter Panel	Repainted
Side mirror	PASS
Foot panel	PASS
Right A Pillar	Repainted
Right B Pillar	Repainted
Right C Pillar	Repainted
Right D Pillar	Repainted

BACK

Right tail-lamp	PASS
Left tail-lamp	PASS
Trunk	Repainted
Bumper	Repainted
Trunk floor	ORIGINAL
Rear windshield	PASS
Rear wiper	PASS
Rear windshield washer	PASS

LEFT

Left Quarter Panel	Repainted
Left Rear Door	Repainted
Left Front Door	Repainted
Left Fender	Repainted
Side mirror	PASS
Foot panel	PASS
Left A Pillar	Repainted
Left B Pillar	Repainted
Left C Pillar	Repainted
Left D Pillar	Repainted

ROOF

Right Roof rail	PASS
Left Roof rail	PASS
Roof	Repainted

SAMPLE

Roof Lining	PASS
Sunroof	NA
Panoramic Roof	PASS

FRONT INTERIOR

Front right seat condition	PASS
Front right electric seat	PASS
Front left seat condition	PASS
Front left electric seat	PASS
Front right seat belt	PASS
Front left seat belt	PASS
Front Flooring Matt	PASS
Right door panel	PASS
Left door panel	PASS
Front interior roof light	PASS

BACK INTERIOR

Rear right seat condition	PASS
Rear right electric seat	NA
Rear left seat condition	PASS
Rear left electric seat	NA
Rear right seat belt	PASS
Rear left seat belt	PASS
Rear Flooring Matts	PASS
Right door panel	PASS
Left door panel	PASS
Rear interior roof light	PASS

DASHBOARD

Dashboard condition	PASS
Steering wheel condition	PASS
Steering wheel control	PASS
Combination Switch (headlamp/Indicator)	PASS
Instrument Cluster	PASS
AC vents (Right)	PASS

SAMPLE

AC vents (Middle)	ATTENTION
AC vents (Left)	ATTENTION
AC control panel	PASS
Air Condition Cooling	PASS
Multimedia	PASS
Center console	PASS
Gloves box compartment	PASS
Rear view mirror	PASS
Right Sun Visor	PASS
Left Sun Visor	PASS

SUSPENSION & STEERING

Front right shock absorbers	Pass
Front left shock absorbers	PASS
Rear right shock absorbers	PASS
Rear left shock absorbers	PASS
Front right control arms	Misting/Noisy
Front left control arms	PASS
Suspension bushes	Misting/Noisy
Ball joints	Misting/Noisy
Steering rack leakage / play	ATTENTION
Steering box	PASS
Power steering	PASS
Wheel bearings and noise	PASS
Wheel alignment	PASS
Suspension road-test response	PASS
Front Air suspension	PASS
Rear Air suspension	PASS

CONDITION MEANINGS

PASS	— No work required	MISTING / NOISY	— Need work required
BLOWN	— Immediately work required	RUST / CORROSION	— Rusty damage

BRAKE

Front Right Brake Pad	Misting/Noisy
Front Left Brake Pad	Misting/Noisy

SAMPLE

Rear Right Brake Pad	PASS
Rear Left Brake Pad	PASS
Brake Calipers	PASS
Brake Fluid Level / Condition	PASS
Brake Fluid Leakage	PASS
Parking Brake / Handbrake	PASS
ABS System	PASS

CONDITION MEANINGS

PASS	— No work required	MISTING / NOISY	— Need work required
BLOWN	— Immediately work required	RUST / CORROSION	— Rusty damage

CHASSIS & ACCIDENT

Front right chassis rail	PASS
Front left chassis rail	PASS
Right apron / inner fender	PASS
Left apron / inner fender	PASS
Rear right chassis rail	PASS
Rear left chassis rail	PASS
Floor pan and underbody	PASS
Undercarriage	PASS
Flood / water damage	PASS

EXHAUST & EMISSIONS

Exhaust Manifold	PASS
Intake Manifold	PASS
Catalytic Converter	PASS
Exhaust Mounts/Hangers	PASS
No Smoke	PASS
White Smoke	NA
Black Smoke	NA

TIRES & WHEELS

Front Right Tire	GOOD
Tire Manufacturing Year	2023
Front Left Tire	GOOD

SAMPLE

Tire Manufacturing Year	2023
Rear Right Tire	GOOD
Tire Manufacturing Year	2023
Rear Left Tire	GOOD
Tire Manufacturing Year	2023
Spare Tire	Available
Wheel / Rim Condition	PASS
Tool Kit	Available

SAFETY SYSTEM (AIRBAGS)

Driver Airbag	ORIGINAL
Driver Knee Airbag	ORIGINAL
Passenger Airbag	ORIGINAL
Passenger Knee Airbag	ORIGINAL
Driver Seat Side Airbag	ORIGINAL
Passenger Seat Side Airbag	ORIGINAL
Rear Seat Airbag	ORIGINAL
Right Curtain Airbag	ORIGINAL
Left Curtain Airbag	ORIGINAL
Right D Pillar Airbag	ORIGINAL
Left D Pillar Airbag	ORIGINAL
Airbag Warning Light	PASS

FEATURES & OPTIONS

Push Button Start	PASS
Keyless Entry	PASS
Remote Start	NA
Cruise Control	PASS
Adaptive Cruise Control	NA
Lane Departure Warning	PASS
Lane Keep Assist	PASS
Blind Spot Monitoring	PASS
Forward Collision Warning	PASS
Automatic Emergency Braking	NA
Front Parking Sensors	PASS

SAMPLE

Rear Parking Sensors	PASS
Front Radar	PASS
Rear View Camera	PASS
360° Camera	PASS
Navigation System	PASS
Apple CarPlay	PASS
Android Auto	PASS
Bluetooth	PASS
Seat Memory	PASS
Heated Seats	PASS
Cooled Seats	PASS
Electric Folding Mirrors	PASS
Traction Control	PASS
Power Windows	PASS
Electronic Parking Brake	PASS
Auto Hold	PASS
Climate Control AC	PASS
All Wheel Drive (AWD)	PASS
4 Wheel Drive (4WD)	PASS

ROAD TEST

Engine Performance / Acceleration	PASS
Transmission Shifting	PASS
Gear Shift Delay	PASS
Gear Shift Jerk	PASS
Steering Performance	PASS
Brake Performance	PASS
Brake Noise	ATTENTION
Abnormal Noise While Driving	PASS
Dashboard Warning Lights During Test	PASS

ISSUES & FINDINGS

ATTENTION

Engine oil level / condition

Need to change



SAMPLE

FAIL **Engine block oil leakage**
Major Leakage



FAIL **Engine head noise**
Major Noise

FAIL **Transmission oil leakage**
Major Leakage



ATTENTION **Bumper**
Repainted

ATTENTION **Bonnet**
Repainted

ATTENTION **Right Fender**
Repainted

ATTENTION **Right Front Door**
Repainted

ATTENTION **Right Rear Door**
Repainted

ATTENTION **Right Quarter Panel**
Repainted

ATTENTION **Right A Pillar**
Repainted

ATTENTION **Right B Pillar**
Repainted

ATTENTION **Right C Pillar**
Repainted

SAMPLE

ATTENTION **Right D Pillar**
Repainted

ATTENTION **Trunk**
Repainted

ATTENTION **Bumper**
Repainted

ATTENTION **Left Quarter Panel**
Repainted

ATTENTION **Left Rear Door**
Repainted

ATTENTION **Left Front Door**
Repainted

ATTENTION **Left Fender**
Repainted

ATTENTION **Left A Pillar**
Repainted

ATTENTION **Left B Pillar**
Repainted

ATTENTION **Left C Pillar**
Repainted

ATTENTION **Left D Pillar**
Repainted

ATTENTION **Roof**
Repainted

SAMPLE

ATTENTION **AC vents (Middle)**
Broken



ATTENTION **AC vents (Left)**
Broken



ATTENTION **Front right control arms**
Misting/Noisy



ATTENTION **Suspension bushes**
Misting/Noisy



ATTENTION **Ball joints**
Misting/Noisy



ATTENTION **Steering rack leakage / play**
Minor noisy


ATTENTION **Front Right Brake Pad**
Misting/Noisy

ATTENTION **Front Left Brake Pad**
Misting/Noisy


ATTENTION **Brake Noise**
Need maintenance

DAMAGE PHOTOS

SAMPLE



Damage photo 1



Damage photo 2

SIGNATURES



Inspector signature



Customer signature

SAMPLE

SCAN TO VIEW INTERACTIVE REPORT

View inspection findings and evidence photos

Open Customer Report